

001131

AIR REPAIR LLC
883 ALLEIGH-BONNETT MEMORIAL DRIVE
SUITE 2125
HUEYTDOWN, AL 36058
Phone: 201-491-1282

CHECK LIST

<input type="checkbox"/> AIR FILTERS <input type="checkbox"/> CLEANED <input type="checkbox"/> REPLACED <input type="checkbox"/> COMPRESSOR <input type="checkbox"/> HOOK <input type="checkbox"/> NEW	<input type="checkbox"/> ELECTRICAL CONNECTIONS <input type="checkbox"/> CONTRACTS TIGHT & CLEAN <input type="checkbox"/> CONDENSATION AREAS <input type="checkbox"/> INSPECT & CLEAN DRAIN <input type="checkbox"/> CONDENSER COIL <input type="checkbox"/> CLEAN COIL & CHECK FAN COND.	<input type="checkbox"/> PILOT ASSEMBLY <input type="checkbox"/> FLAME ADJUSTMENT <input type="checkbox"/> PRIMARY RELAY & FUSE <input type="checkbox"/> FAN & LIMIT SWITCH OPER <input type="checkbox"/> BLOWER ASSEMBLY <input type="checkbox"/> IN VALVE <input type="checkbox"/> STRIP HEAT <input type="checkbox"/> DEFROST CYCLE <input type="checkbox"/> REFRIGERANT <input type="checkbox"/> TSHK <input type="checkbox"/> CHARGE <input type="checkbox"/> THERMOSTAT <input type="checkbox"/> OK <input type="checkbox"/> REPLACE
--	--	---

NAME: Steven Jones
ADDRESS: 6920 W. 8th St. Dr. N.E.
CITY: Princeton STATE: NC
ZIP: 27574
PHONE: 35726
WORK PHONE: 35726

ITEM OR PART DESCRIPTION: W-54 Del-T
4270-73010206-0081
EXP 10-09

TOTAL PARTS

DESCRIPTION	AMOUNT
024200W AKD2 00-03	

INSPECTION CHECKLIST

TYPE	REPAIR	RECOVERED?	RECYCLED?	RECLAIMED?
NOV. USABLE	YES	NO	YES	NO
QTY.				
DISPOSAL				

DATE: 7-16-07
DATE ORDERED: 7-16-07
DATE SCHEDULED: 7-16-07
TECHNICIAN: PH Jones
TOTAL CHARGES: \$55.00
SUB-TOTAL: \$55.00
TAX: \$0.00
TOTAL DUE: \$55.00

2007 Dec-03
U.S. DISTRICT COURT
N.D. OF ALABAMA

DATE: 7-16-07
TIME: 10:30 AM
LOCATION: Princeton, NC
TECHNICIAN: PH Jones
TOTAL CHARGES: \$55.00
SUB-TOTAL: \$55.00
TAX: \$0.00
TOTAL DUE: \$55.00

DATE: 7-16-07
TIME: 10:30 AM
LOCATION: Princeton, NC
TECHNICIAN: PH Jones
TOTAL CHARGES: \$55.00
SUB-TOTAL: \$55.00
TAX: \$0.00
TOTAL DUE: \$55.00

S/C W/O A/C Unit has started service - Contact has been made. Unit is clogged due to not having a proper filter rock in system. Condenser coil is also clogged with dirt & surface. If the price of \$5,650 for the new unit is not acceptable, we will refund \$3,000.00 for a condenser unit. Unit has been replaced with a new one. All parts are covered by warranty.

LABOR CHARGES: \$55.00
TECHNICIAN SIGNATURE: [Signature]
CERTIFICATE NO. PH Jones
I HEREBY AUTHORIZE THE ABOVE WORK TO BE DONE AS SO ORDERED AND OUTLINED ABOVE. I AGREE THAT THE ABOVE WORK SHALL BE DONE TO ANY EQUIPMENT ON MATERIAL FURNISHED BY THE CUSTOMER. THE CUSTOMER HAS BEEN MADE AWARE OF THE FACT THAT THE CUSTOMER HAS THE RIGHT TO REQUEST A REFUND OF THE ABOVE CHARGES IF THE CUSTOMER IS NOT SATISFIED WITH THE RESULTS OF THE WORK. THE CUSTOMER HAS BEEN MADE AWARE OF THE FACT THAT THE CUSTOMER HAS THE RIGHT TO REQUEST A REFUND OF THE ABOVE CHARGES IF THE CUSTOMER IS NOT SATISFIED WITH THE RESULTS OF THE WORK.